




KPI



JOB RECORD
LAND



JOB RECORD
PPTY



CFS



CI/MI

View Key Performance Indicators (KPI) at a glance

[Back](#)

Feedback Details

Feedback ID: 2018-07493 Date Received: 22/6/2018 12:00:00 AM

Feedback Content: Mr Tan has feedback that there is a beehive on the state land just beside his company. It is posing inconvenience and potential danger of bee stung for his staff and customers. He requested for the Area Officer to give him a call to arrange for a site meeting, asap. Thank you.

User Details

Company Details

Other Details

Add Response

Type: Interim Response

Description

Swift access to full feedback details

Add Response

< Back

User Details

Company Details

Other Details

Add Response

Type

Interim Response

Description


We are looking into it



Provide rapid response on the go

iPad 1:21 PM 39%

< Back


PENDING 2018-06-25 12:20:49... 

- > CFS 2
- ▼ JR 13
- > MK31 LAND 11 PPTY 0
- > MK32 LAND 1 PPTY 0
- ▼ TS29 LAND 0 PPTY 1


Asset ID: TS29NV106457
Description: 50 JALAN TAN TOCK SENG
Category: Ppty

COMPLETED 2018-06-25 12:20:49...

- > MK29
- > MK31
- > TS28
- > TS29



Licensed for Developer Use Only



Back

Job Record - TS29NV106457



S.NO	ITEM	PERFORMANCE REVIEW RATING		
1	Remove all weeds and undesirable vegetation, in...	10	5	0
2	Cut and maintain all turfed areas in the Sites incl...	10	5	0
3	Close cut all grass within the Site in such a way t...	10	5	0
4	Backfill and level all depressed beds/areas/potho...		5	0
5	All grass growing around trees, shrubs, palms, ro...		5	0
6	Strip and clear all the vegetation and undergrowt...	10	5	0
7	All grass clippings, overgrown vegetation and wa...	10	5	0
8	The disposal of all debris, rubbish, rubble, shrub...		5	0


0 Non Performance 5 Performed but not satisfactorily 10 Completed Satisfactorily **TOTAL SCORE 60**

Add Photo (Max 10) Add Video (Max 10 sec)

Comment (Mao Sheng Quanji Construction Pte Ltd)

Send Feedback Next

Systematic work performance rating & documentation



← Back

Add Layers

- Land Ownership
- Asset Management Layer
- Major TA/TOL
- Managing Agent
- Lamp Post
- LTA Road Kerb Line
- Existing PUB Drainage Line
- PUB Drainage Reserve Line
- LTA Road Centre Line

Licensed for Developer Use Only

Improve locational awareness with geospatial data at fingertips

[← Back](#)

Workflow for Demerit points and LD	(i) >
Workflow for Grasscutting (LEM and PPM)	(i) >
Workflow for maintenance of vacant state land and properties	(i) >
Workflow for Patrolling (LEM)	(i) >
Workflow for return of state land and buildings	(i) >
Workflow on handling feedbacks on bees,wasps,hornets	(i) >
Workflow to manage Asset Management Layer	(i) >
Land Inspection and Maintenance of Vacant State Land workflow	(i) >
Letter informing resident of tree cutting works	(i) >
Mosquito Breeding and Requests for Site Clearing Response Letter	(i) >
NOTIFICATION FORM FOR RETURN OF VACANT LAND	(i) >
Template for Approval of Works	(i) >
Flowchart for Maintenance of State Land	(i) >
Flowchart-Urgent work	(i) >
Access updated best practice guides whenever required	
LEM Work Instruction - 100 Percent Check Every Quarter	(i) >